Water not safe to drink

The following unregulated wells were tested by the U.S. Environmental Protection Agency, Navaio Nation EPA, or the Center for Disease Control and found to contain unsafe levels of Uranium.

People should not drink water from these wells:

Well ID

16B-38 (CCC-E-9) 16T-521-Platero Well

Badger Spring (Black Falls)

Paddock Well (Black Falls)

3A-155-Tohatchi Spring (Black Falls)

16-4-10-Lime Ridge/Pine Tree Well

17M-99 (ID not on well)

12-7-12-Ellison Dug Well

8A-179 08A-180

17M-66 (Ganado)

8K-433-Old Number 8A-299

5M-74-Box Springs (Black Falls)

17T-559 Lower Greasewood

10T-241A

Monument Pass Well

9Y-12

9Y-32

16T-519-Largo Corral Well

9T-550

9T-586

10R-51 B

Chapter

Baca, N.M. Baca, N.M.

Cameron, Ariz.

Cameron, Ariz.

Cameron, Ariz.

Churchrock, N.M.

Cornfields, Ariz.

Cove. Ariz.

Dennehotso, Ariz.

Dennehotso, Ariz.

Ganado, Ariz.

Kayenta, Ariz.

Leupp, Ariz.

Greasewood

Many Farms

Oljato, Utah

Red Mesa, Ariz.

Red Mesa, Ariz.

Smith Lake, N.M.

Sweetwater, Ariz.

Sweetwater, Ariz.

Tselani, Ariz.

Other contaminants that are harmful to humans have been frequently found in livestock wells. Navajo Nation policy is that livestockuse-only wells are not to be used for human drinking water.

For more information about livestock well sampling results and

regulated sources of safe drinking water, please contact: Navajo Public Water System Supervision Program

(928) 871-7715

www.navaiopublicwater.org